



**SCRANTON MUSEUM - BOAT
 PASCAGOULA RIVER PARK**

TRANSITION PLAN

ITEM #	SECTION #: GROUP	NON-COMPLIANCE DESCRIPTION	COMMENTS / SUGGESTED CORRECTIONS	PRIORITY	COST CODE	BUDGET COST	COMPL. DATE	PHOTOGRAPHS
1	405 Ramp	1. First leg of ramp > 8.33% slope.	1. Correct ramp slope to 8.33% (1:12) max.		RMP	\$ 500		
2	402 Accessible Routes	1. 45° brace to rail a trip hazard. 2. Platform to boat entry a possible trip hazard. (change in elevation)	1. Provide rail or knee wall at each brace.		OL	\$ 150		

REPORT TOTAL: \$ 650